Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

921 SPILL NUMBER 0003663 NY Spills S104650981 WSW 2877 W. 36TH ST N/A

> 1 BROOKLYN, NY 1.231 mi. 6502 ft.

Relative: SPILLS: Higher Name

 Higher
 Name:
 SPILL NUMBER 0003663

 Actual:
 Address:
 2877 W. 36TH ST

 0 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0003663 / 2001-09-27

 Facility ID:
 0003663

 Facility Type:
 ER

 DER Facility ID:
 83601

 Site ID:
 93225

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2000-06-25

 Investigator:
 JHOCONNE

 Referred To:
 Not reported

 Reported to Dept:
 2000-06-25

 CID:
 322

Water Affected: Not reported Spill Source: Commercial/Industrial Spill Notifier: Responsible Party Not reported Cleanup Ceased: Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0

Date Entered In Computer: 2000-06-25
Spill Record Last Update: 2001-10-10
Spiller Name: BRIAN JOYCE
Spiller Company: CON ED

Spiller Address: 4 IRVING PLACE

Spiller Company: 001

Contact Name: Not reported

DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was
O'CONNELL Con Ed e2mis Notes: 6/25/00 1 pint dielectric fluid spilled
from overhead transformer. A 30'X10' area was affected, with oil

from overhead transformer. A 30'X10' area was affected, with oil drops on sidewalk, curb, street and grass between sidewalk and street. No customer property affected. Appears to be non-PCB due to August 1991 date on transformer, however a sample is being taken. Crew bagged unit and took sample. Double washed sidewalk and barrelled debris. Also dug up grass. Sample returned <1ppm PCB. (KMF

10/10/01)"

Remarks: "OVERHEAD TRANFORMER HAD 1 PT LEAK TO SIDEWALK - SPILL IS BEING

CLEANED UP AT 50/499 PPM PCB - CON ED 132006"

All Materials:

 Site ID:
 93225

 Operable Unit ID:
 826061

 Operable Unit:
 01

 Material ID:
 551980

 Material Code:
 0541A

 Material Name:
 dielectric fluid

 Case No.:
 Not reported

Map ID Direction Distance

Site

Elevation

## MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

Material FA: Petroleum Quantity: 1.00 Units: G Recovered: .00

Oxygenate: Not reported